

CIL
EMU CRITICAL ITEMS LIST

12/26/94 SUPERSEDES 12/24/92

Page: 1
Date: 11/10/94

ANALYST:

NAME	P/N	QTY	CBIT	FAILURE	FAILURE EFFECT	RATIONALE FOR ACCEPTANCE
POWER MODE SELECTOR SWITCH, ITEM 364 8V770596-4 (1)		2/2		364FH01: Stationary in SCU position. CAUSE: Switch mechanism jammed due to contamination, cold welding in vacuum, part failure.	END ITEM; Unable to switch to battery at start of EVA or during checkout sequence. GFE INTERFACE: Unable to operate on battery mode.	A. Design - Each of the three switches is tested in a dry nitrogen filled hermetically sealed case. The switches are per MIL-A-8805/46 except that the 10 amp contacts are silver plated. Switch contact rated for 10 amperes. Actual current flow is 3.7 amperes. The handle is designed to withstand a toggle force of 25 lbs. without degradation in subsequent performance. The ball socket of the toggle pivot is greased (Fraycoat 601) prior to assembly. MISSION: Terminate EVA. Loss of use of one EMU. CREW/VEHICLE: None.
						B. Test - Component Acceptance Test - Switch operation and continuity are verified during vendor acceptance tests. The switch is also subjected to 500 run-in cycles and an axial pull test on the handle. In-Process Test - Operation and integrity of the switch are verified during four separate in-process tests during initial item 350 assembly. These tests include continuity and output voltage. The switch is cycled during these tests. PQA Test - The switch is subjected to Acceptance/PQA testing as part of item 350. Tests include continuity, operating torque, vibration, thermal cycling, and thermal vacuum. The switch is also cycled during item 350 Acceptance/PQA electrical functional tests. Certification Test - The item completed 5,469 inductive and 0,536 resistive cycles during 1/81 which satisfied the cycle certification requirement of 5,464 and 0,536 respectively. Class I Engineering Change 42805-366 (Toggle handle pull test) has been incorporated since this configuration was certified. C. Inspection - To preclude failure due to internal contamination, the switches are assembled by the vendor in an environmentally controlled room. Assembly and processing is per MIL-S-8805/46. The switches receive in-process cycling and

CTL
EMU CRITICAL ITEMS LIST

12/26/94 SUPERSEDES 12/26/92

Page: 2
Date: 11/10/94

ANALYST:

NAME	FAILURE	CAUSES	FAILURE EFFECT	RATIONALE FOR ACCEPTANCE
P/N	MODE 6			
QTY	CRIT	CAUSES		
2/2	364FM01			Leak checks. The entire item 364 is x-ray inspected for acceptability of braising.
				D. Failure History - J-EMU-300-006 (10-18-83) The BITE light failed to turn on upon power switchover during PIA tests. This outage was found to be caused by a mechanical failure of Power Mode switch (364) which prevented proper power switchover. EC 42826-3B6 added a pull test to the 364 vendor test to insure the normal use. This EC created the -2 switch configuration.
				E. Ground Turnaround - Tested during FEMU-R-001 EMU Vacuum Chamber Run, Orbiter Power Interface, and SEMU Comm & Biomed Check.
				F. Operational Use - Crew Response - PreEVA: Trouble shoot problem, if no success, consider third EMU if available. Otherwise, EMU go for ECU standby. Training - Standard training covers this failure mode. Operational Considerations - EVA checklist procedures verify hardware integrity and systems operational status prior to EVA. Flight rules define go/no go criteria related to EMU battery power. Real Time Data System allows ground monitoring of EMU systems.